

Improvements to 85 Cedar Bay Drive since 2009

2009

- Changed all interior doors and moldings
- Renovated master suite including bathroom
- Installed oak floors on stairway to second floor and second floor bedrooms

2011

- Replaced deck supports
- Renovated lavette to coordinate with kitchen
- Replaced deck balusters and lattice

2012

- Replaced mini-split heat/air-conditioning system for first floor

2013

- Replaced boiler
- Renovated rear bedroom

2015

- Renovated basement walkout room: installed closets, flooring, dry bar, wine chiller, gas fireplace
- Installed patio and stone knee wall
- Renovated second floor bathroom
- Replaced washing machine and gas dryer

2018

- Replaced refrigerator, stove, microwave, dishwasher

2019

- Replaced hot water heater
- Resurfaced driveway with 3 inch asphalt
- Renovated laundry room